

COMPLIANCE DOCUMENT



South Asia

This Compliance Document is issued to:

M/s. KLAUS MULTIPARKING SYSTEMS PVT. LTD.
GAT NO. 1271/72/73, AT POST - SHIRWAL,
TAL: KHANDALA DIST: SATARA 412801, INDIA

Choose certainty.
Add value.

FOR

Product : PARKING SYSTEM -

Model No. : 3015

Test Standards : EN 14010:2003+A1:2009 &
EN 61000-6-3:2007+A1: 2011

Test Report No. BLR/ENE/SAF/22/1878945
BLR/ENE/EMC/22/1878945

This is to confirm that a sample of machine was tested to the safety test requirements of Machinery Directive (2006/42/EC), Low voltage directive (2014/35/EU) and EMI/EMC Directive (2014/30/EU) by us at the manufacturing location.



After implementation of the requirements as per test report no. BLR/ENE/SAF/22/1878945 and BLR/ENE/EMC/22/1878945 issued to the manufacturer, preparation of the necessary technical documentation and signing of the declaration of conformity, CE marking can be affixed on the product. Other relevant directives have to be observed.

The document holder is responsible for the consistent manufacturing of the product in compliance with the test sample submitted to us.

SGM-PRODUCT SERVICE - ENE

Ref No.
CD/1878945

Date of Original Issue
04th March 2022

Date of revision:

Note: Products entering the European Union are subject to the requirements set forth in the European Directives. It is the responsibility of the person placing the product on the European market to ensure compliance with applicable Directives. The requirements of directives and standards change from time to time and it is the responsibility of the manufacturer to ensure compliance. Our services are intended to provide you with the data needed to determine compliance, but the person placing the product on the European market still has the responsibility to ensure each product complies with the applicable Directives. The product liability rests with the manufacturer or his representative in accordance with Council Directive 85/374/EEC.

This document applies only to the particular model provided for testing and CE certification and does not permit the use of a TÜV PRODUCT SERVICE certification mark. It becomes ineffective in the event of changes relating to products, applicable standards and the Directives.

TÜV SÜD South Asia Pvt. Ltd. · TÜV SÜD Group · Off. Saki Vihar Road, Saki Naka · Andheri (East) · Mumbai – 400 072 · India